

EPA ID: NJD061056198 Site Name: EDISON STAMPING &amp; MANUFACTURING CO.

State ID:

Alias Site Names:

City: SOUTH PLAINFIELD

Refer to Report Dated: 1/22/2009

County or Parrish: MIDDLESEX

State: NJ

Report Developed By:

Report Type: PRELIMINARY ASSESSMENT 001

☐ 1. Further Remedial Site Assessment Under CERCLA (Superfund) is not required because:☒ 2. Further Assessment Needed Under CERCLA:


Higher priority for further assessment

**Discussion/Rationale:**

The Edison Stamping and Manufacturing Co. (ESM) manufactured metal parts for various Industry (i.e. aerospace, automobile). Edison Stamping (ESM) purchased the site from Kleiner Metal on 1968. It is likely that Edison Stamping used Tetrachloroethene (PCE), though document records have yet to be located. A consultant report asserts that sanitary wastes generated at the 4490 Stelton Rd. site were disposed in a septic tank, when EMS connected to a municipal sewer system. PCE was detected in a private home along Franklin Street in the vicinity of ESM. In 1990, residents were connected into a public water line. Based on the information, a Site Inspection (SI) is recommended for the Edison Stamping site, to determine if ESM is the source of the PCE contamination in the Franklin Avenue wells.

Site Decision Made by: JAMES DESIR

Signature: \_\_\_\_\_



Date: 01/29/2009

203971

